

Gown

taking PPE OFF



(ACE)

1 **Wipe** outer gloves.

2 **Sanitize** outer gloves.

3 **Remove** boot covers.

4 **Sanitize** outer gloves.

5 **Roll** the gown towards your hands.

Remove the outer gloves with the gown.

Dispose of outer gloves and gown.

Face Shield

6 **Sanitize** inner gloves.

8 **Wipe** front and back of shield.

9 **Wipe** elastic band.

10 **Wipe** foam band.

11 **Wipe** table.

12 **Place** shield upside down to dry.

7 **Remove** face shield without touching front of shield.

Gloves + Mask

13 **Sanitize** inner gloves.

14 **Remove** bouffant and dispose.

15 **Sanitize** inner gloves.

16 **Remove** under gloves and dispose.

EXIT operating room (use runner to open door)

17 **Wash** hands with soap and water for 20sec.

18 **Remove** N95, lower strap and then upper. Avoid touching front of mask. **Store** mask.

19 **Sanitize** hands.

20 **Go** to locker room and **dispose** of scrubs.

Shower before leaving.