

Putting PPE ON



(ACE)



Cloth hat



Boot covers



N95 Respirator



Outer gloves



Bouffant cap



Face shield



Inner gloves



Surgical gown

What You Need

OR Prep

1

Remove any personal items, including earrings, necklaces, rings, etc.



2

Put on cloth hat.




3

Put on boot covers.



4

Sanitize hands.



Mask

4


Put on N95. **Ensure** straps are not crossing.



5

Place hands over the front of the N95. **Breathe** an easy deep breath in and out.

If you **feel** air escape the edges, **refit** and **repeat**.



6

Put on bouffant cap.



Face Shield

7

Put on face shield.



8

Remove comm. devices, such as cell phones, pagers, and ID badge.



Check for good fit with **PPE Champion**.



9

Perform standard surgical scrub.



ENTER operating room (use runner to open door)

Gown + Gloves

11

Put on first pair of sterile gloves.



12

Put on surgical gown with circulator's help.

Circulator in non-sterile PPE.



13

Put on second pair of sterile gloves over gown cuffs.

